


Mat.: HSS

90°

α STD=0°

180°

0°



270°

1341 - d₂ x L₁ x Typ_ x a x b x R x α

L	d ₃	d ₄ max	d ₂	L ₁ =16	L ₁ =20	L ₁ =22	L ₁ =25	L ₁ =28	L ₁ =30	L ₁ =32	L ₁ =35	Form B		Form C	
												a	b _{min}	G _{max}	
2	8	2,8	5	■	■	■	■	■	■	■	■	1,0 - 2,4			
3	9	3,5	6	■	■	■	■	■	■	■	■	1,6 - 3,0			
4	11	4,0	8	■	■	■	■	■	■	■	■	2,0 - 3,5	1,2	3,5	
4	13	5,8	10	■	■	■	■	■	■	■	■	3,0 - 5,0	1,2	5,0	
5	16	8,0	13		■	■	■	■	■	■	■	4,0 - 7,0	2,0	7,0	
5	19	9,5	16		■	■	■	■	■	■	■	6,0 - 9,0	2,4	9,0	
8	23	12,0	20		■	■	■	■	■	■	■	8,0 ÷ 11,0	3,2	11,0	
8	25	15,0	22		■	■	■	■	■	■	■	9,0 ÷ 14,0	4,0	14,0	
8	28	17,3	25		■	■	■	■	■	■	■	10,7 ÷ 16,0	4,8	16,0	
8	35	20,7	32		■	■	■	■	■	■	■	15,0 - 20,0	5,5	20,0	
8	43	27,7	40		■	■	■	■	■	■	■	19,0 - 27,0	6,4	27,0	