


2532

KERN 20
PART SERVER 30



Mat.: Ms

PHASING OUT




2532 - d_2

L_1	L_3	SW	d_6	d_2
13	9	19	G3/8A	G1/4
18	12	24	M24x1,5	M16x1,5
24	16	27	G3/4A	G1/2

2533

KERN 20
PART SERVER 30



Mat.: Ms



2533 - $d_2 \times d_6$

d_3	d_2	d_6
6	10	M10x1
		G1/8
		G1/4
8	13	M12x1,5
G1/4		
9	13	M14x1,5
		G3/8