


Mat.: HSS



90°

$\alpha$  STD=90°



1356 -  $d_1 \times L_1$  / Typ  $\times a \times b \times R \times L_2 \times \alpha$

$d_5$	$d_1$	$L_1=63$	$L_1=71$	$L_1=80$	$L_1=90$	$L_1=100$	Form B		Form C		$L_2$		
							$a$	$b_{min}$	$G_{max}$				
6	6	■	■	■	■	■	1,60 - 5,99	1,6	5,9	8	10	13	
8	10	■	■	■	■	■	4,00 - 9,99	1,6	9,9	10	13	19	
8	13	■	■	■	■	■	5,00 - 12,99	4,5	12,9	10	13	19	
8	16	■	■	■	■	■	8,00 - 15,99	6,0	15,9	13	19	25	
8	20	■	■	■	■	■	12,00 - 19,99	8,0	19,9	13	19	25	
8	25	■	■	■	■	■	16,50 - 24,99	10,0	24,9	13	19	25	